



[별첨1] 측정 위치도(측정 장소)

|                                |      |          |
|--------------------------------|------|----------|
| 군산시 구암동 공동주택 개발계획 신축공사 석면해체 제거 | 측정일시 | 22.03.21 |
|--------------------------------|------|----------|



|    |      |  |   |
|----|------|--|---|
| 범례 | *NO  |  |  |
|    | 시료채취 | 부지경계선  | 대상건축물   |

[별첨2] 측정 결과

| 시료<br>번호 | 측정 지점            | 측정 장비<br>(종류/수량)      | 유량<br>(l/분) | 측정 일시 | 측정 결과<br>(f/cc) | 비고                |   |
|----------|------------------|-----------------------|-------------|-------|-----------------|-------------------|---|
| *1       | 부지경계선1           | 지역시료채취펌프<br>SARA-5100 | 1           | 9.79  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *2       | 부지경계선2           | 지역시료채취펌프<br>SARA-5100 | 1           | 9.92  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *3       | 부지경계선3           | 지역시료채취펌프<br>SARA-5100 | 1           | 9.78  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *4       | 부지경계선4           | 지역시료채취펌프<br>SARA-5100 | 1           | 9.74  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *5       | 위생설비입구           | 지역시료채취펌프<br>SARA-5100 | 1           | 9.54  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *6       | 작업장주변            | 지역시료채취펌프<br>SARA-5100 | 1           | 9.95  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *7       | 음압기배출구1<br>(사무동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.63  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *8       | 음압기배출구2<br>(사무동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.64  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *9       | 폐기물반출구1<br>(사무동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.97  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *10      | 폐기물반출구2<br>(사무동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.52  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *11      | 폐기물반출구3<br>(공장동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.67  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *12      | 폐기물보관지점1         | 지역시료채취펌프<br>SARA-5100 | 1           | 9.89  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *13      | 폐기물보관지점2         | 지역시료채취펌프<br>SARA-5100 | 1           | 9.58  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| *14      | 폐기물보관지점3         | 지역시료채취펌프<br>SARA-5100 | 1           | 9.79  | 22/03/21        | 불검출[검출한계 0.002미만] |   |
| -        | 공시료              | -                     | -           | -     | -               | 0개/100개시야         | - |
| -        | 공시료              | -                     | -           | -     | -               | 0개/100개시야         | - |
| 비고       |                  |                       |             |       |                 |                   |   |

[별첨3] 측정 사진. (측정일시 : 2022.03.21)

| 측정 지점                  | 시작 사진  | 종료 사진  | 시작 사진   | 종료 사진  |
|------------------------|--|--|---|--|
| 부지경계선<br>1,2           | <br>10:00   | <br>14:10   | <br>10:02   | <br>14:12   |
| 부지경계선<br>3,4           | <br>10:04   | <br>14:14   | <br>10:06   | <br>14:16   |
| 위생설비입구<br>/<br>작업장주변   | <br>10:10  | <br>10:55  | <br>10:15  | <br>12:25  |
| 음압기배출구<br>1,2<br>(사무동) | <br>10:20 | <br>11:05 | <br>10:22 | <br>11:07 |
| 폐기물반출구<br>1,2<br>(사무동) | <br>11:50 | <br>12:35 | <br>14:00 | <br>14:45 |

[별첨3] 측정 사진

| 측정 지점                                 | 시작 사진  | 종료 사진  | 시작 사진   | 종료 사진  |
|---------------------------------------|--|--|---|--|
| 폐기물반출구3<br>(공장등)<br>/<br>폐기물<br>보관지점1 | <br>15:00 | <br>15:45 | <br>15:10 | <br>15:55 |
| 폐기물<br>보관지점<br>2,3                    | <br>15:15 | <br>16:00 | <br>15:20 | <br>16:05 |

[별첨1] 측정 위치도(측정 장소)

|                                |      |          |
|--------------------------------|------|----------|
| 군산시 구암동 공동주택 개발계획 신축공사 석면해체 제거 | 측정일시 | 22.03.22 |
|--------------------------------|------|----------|







|    |      |  |   |
|----|------|--|---|
| 범례 | *NO  |  |  |
|    | 시료채취 | 부지경계선  | 대상건축물   |

[별첨2] 측정 결과









| 시료<br>번호 | 측정 지점             | 측정 장비<br>(종류/수량)      | 유량<br>(l/분) | 측정 일시 | 측정 결과<br>(f/cc) | 비고                |   |
|----------|-------------------|-----------------------|-------------|-------|-----------------|-------------------|---|
| *1       | 부지경계선1            | 지역시료채취펌프<br>SARA-5100 | 1           | 9.69  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *2       | 부지경계선2            | 지역시료채취펌프<br>SARA-5100 | 1           | 9.74  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *3       | 부지경계선3            | 지역시료채취펌프<br>SARA-5100 | 1           | 9.72  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *4       | 부지경계선4            | 지역시료채취펌프<br>SARA-5100 | 1           | 9.89  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *5       | 위생설비입구            | 지역시료채취펌프<br>SARA-5100 | 1           | 9.72  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *6       | 작업장주변             | 지역시료채취펌프<br>SARA-5100 | 1           | 9.57  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *7       | 폐기물반출구1<br>(공장동)  | 지역시료채취펌프<br>SARA-5100 | 1           | 9.87  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *8       | 폐기물반출구2<br>(공장동)  | 지역시료채취펌프<br>SARA-5100 | 1           | 9.80  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *9       | 폐기물반출구3<br>(공장동)  | 지역시료채취펌프<br>SARA-5100 | 1           | 9.70  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *10      | 폐기물보관지점1<br>(사무동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.82  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *11      | 폐기물보관지점2<br>(공장동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.87  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *12      | 폐기물보관지점3<br>(공장동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.62  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| *13      | 폐기물보관지점4<br>(공장동) | 지역시료채취펌프<br>SARA-5100 | 1           | 9.87  | 22/03/22        | 불검출[검출한계 0.002미만] |   |
| -        | 공시료               | -                     | -           | -     | -               | 0개/100개시야         | - |
| -        | 공시료               | -                     | -           | -     | -               | 0개/100개시야         | - |

비 고

[별첨3] 측정 사진. (측정일시 : 2022.03.22)

| 측정 지점  | 시작 사진  | 종료 사진  | 시작 사진   | 종료 사진  |
|--|--|--|---|--|
| 부지경계선<br>1,2                                   | <br>8:50    | <br>13:00   | <br>8:55    | <br>13:05   |
| 부지경계선<br>3,4                                   | <br>9:00    | <br>13:10   | <br>9:05    | <br>13:15   |
| 위생설비입구<br>/<br>작업장주변                           | <br>9:10   | <br>9:55   | <br>9:15   | <br>11:25  |
| 폐기물반출구<br>1,2<br>(공장동)                         | <br>10:00 | <br>10:45 | <br>10:30 | <br>11:15 |
| 폐기물반출구3<br>(공장동)<br>/<br>폐기물<br>보관지점1<br>(사무동) | <br>10:50 | <br>11:35 | <br>15:00 | <br>15:45 |

[별첨3] 측정 사진

| 측정 지점                       | 시작 사진   | 종료 사진   | 시작 사진  | 종료 사진   |
|-----------------------------|---|---|--|---|
| 폐기물<br>보관지점<br>2,3<br>(공장동) |  |  |  |  |
|                             | 15:05   | 15:50   | 15:10  | 15:55   |
| 폐기물<br>보관지점<br>4<br>(공장동)   |  |  |  |  |
|                             | 15:15   | 16:00   | -  | -   |

[별첨1] 측정 위치도(측정 장소)

|                                |      |          |
|--------------------------------|------|----------|
| 군산시 구암동 공동주택 개발계획 신축공사 석면해체 제거 | 측정일시 | 22.03.23 |
|--------------------------------|------|----------|













|    |      |  |   |
|----|------|--|---|
| 범례 | *NO  |  |  |
|    | 시료채취 | 부지경계선  | 대상건축물   |

[별첨2] 측정 결과

| 시료<br>번호 | 측정 지점    | 측정 장비<br>(종류/수량)      | 유량<br>(l/분) | 측정 일시 | 측정 결과<br>(f/cc) | 비고                |   |
|----------|----------|-----------------------|-------------|-------|-----------------|-------------------|---|
| *1       | 폐기물보관지점1 | 지역시료채취펌프<br>SARA-5100 | 1           | 9.65  | 22/03/23        | 불검출[검출한계 0.002미만] |   |
| *2       | 폐기물보관지점2 | 지역시료채취펌프<br>SARA-5100 | 1           | 9.97  | 22/03/23        | 불검출[검출한계 0.002미만] |   |
| *3       | 폐기물보관지점3 | 지역시료채취펌프<br>SARA-5100 | 1           | 9.88  | 22/03/23        | 불검출[검출한계 0.002미만] |   |
| *4       | 폐기물보관지점4 | 지역시료채취펌프<br>SARA-5100 | 1           | 9.92  | 22/03/23        | 불검출[검출한계 0.002미만] |   |
| *5       | 폐기물보관지점5 | 지역시료채취펌프<br>SARA-5100 | 1           | 9.67  | 22/03/23        | 불검출[검출한계 0.002미만] |   |
| -        | 공시료      | -                     | -           | -     | -               | 0개/100개 시야        | - |
| -        | 공시료      | -                     | -           | -     | -               | 0개/100개 시야        | - |
| 비 고      |          |                       |             |       |                 |                   |   |

[별첨3] 측정 사진. (측정일시 : 2022.03.23)

| 측정 지점              | 시작 사진  | 종료 사진  | 시작 사진  | 종료 사진   |
|--------------------|--|--|--|---|
| 폐기물<br>보관지점<br>1,2 | <br>8:00  | <br>8:45  | <br>8:05 | <br>8:50 |
| 폐기물<br>보관지점<br>3,4 | <br>8:10  | <br>8:55  | <br>8:15 | <br>9:00 |
| 폐기물<br>보관지점<br>5   | <br>8:20 | <br>9:05 | -  | -   |